

FITNESS CERTIFICATE

(To be filled by the Inspecting Officer - Assistant Engineer)

- 1 Name of the Officer : AJITHA P KUMARAN
- 2 Name of the School : MONTFORT VALLEY SCHOOL , MURIKKUMTHOTTY
- 3 Location with name of Education District/Sub.District : KATTAPPANA
- 4 Classification of Building as specified in column 4 of the application for fitness certificate and size :
- RCC FRAMED STRUCTURE :
- BASE MENT 2 17.80x9.70M
- BASEMENT 1 31.10x9.70M
- GROUND , FIRST &SECOND 51.30x9.70M (3 floors)
- GROUND , FIRST &SECOND 19.50x9.70M (3 floors)
- 5 Period for which the certificate is issued : 2025-26
- 6 Nature of defects ,if any :
- a) Foundation and basement : NIL
- b) Superstructure : NIL
- c) Doors and Windows : NIL
- d) Wood work wrought and put u : NIL
- e) Roof : NIL
- f) Flooring : NIL
- g) Miscellaneous (Cracks, etc.) : NIL
- 7 Any major defects notified : NIL
- 8 Whether maintenance works have been done properly : YES
- 9 Whether the structure is sound or not for conducting classes : structure is sound for functioning , under normal weather condition .

Note: 1.The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.2.Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by on 05/05/2025 and found to be fit / ~~unfit~~ to conduct classes, for the period 2025-26 for the reasons stated above.




**ASSISTANT ENGINEER
LSGD SECTION
RAJAKUMARI**